

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- ✓ • TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIG. 1

RABIN & BERDO, P.C.
 CUSTOMER NO: 23995
 APPLICANT: Chung-Ming TSAO
 TITLE: FLASHLIGHT LAMP
 FILED: December 2, 2003
 ATTY DKT. NO. TAIW 198




FIG.2

RABIN & BERDO, P.C.
CUSTOMER NO: 23995
APPLICANT: Chung-Ming TSAO
TITLE: FLASHLIGHT LAMP




FIG. 3

**RABIN & BERDO, P.C.
CUSTOMER NO: 23995
APPLICANT: Chung-Ming TSAO
TITLE: FLASHLIGHT LAMP**
**FILED: December 2, 2003
ATTY DKT. NO. TAIW 198**




FIG. 4

RABIN & BERDO, P.C.
CUSTOMER NO: 23995
APPLICANT: Chung-Ming TSAO
TITLE: FLASHLIGHT LAMP




FIG. 5